

doc00294220171130100012.pdf

UNCLASSIFIED

s 22

FYI please see attached Incident Report from Driver s 22 in relation to the damage caused at the Senate on 29/11

s 22

s 22

COMCAR

Department of Finance

s 22

A: Building 6, Wetlands Foreshore, 1 Dairy Road, FYSHWICK ACT 2609

UNCLASSIFIED



Australian Government
Comcover

Comcover Member Services

Motor Vehicle Claim Report

Section A Member Agency Details

Member Agency Name

Details of person within member agency to contact concerning the claim:

Name

Business Address

Telephone

Fax

Email

Date that you or the organisation first became aware of the claim

/ /

Section B Driver Details *

Name of Driver

Business Address

Telephone

Licence Number

Is the driver named above the principal driver?

☒ Yes

☐ No

Did the driver consume any alcohol or take any drugs within 12 hours prior to the accident?

☐ Yes

☒ No

Did the Police perform a breath or blood test?

☐ Yes, if so please state the reading below

☒ No

Section C Member Vehicle Details *

Please indicate the cover that applies to you/vehicle

☐ Comprehensive (repairs to your vehicle **are** covered under the policy)

☐ Third Party Property damage only (repairs to your vehicle **are not** covered under the policy)

Vehicle Registration Number

s 22

Make and Model **HOLDEN CAPRICE**

Year

Colour **WHITE**

Odometer reading

Number of occupants (including the driver) at the time of the incident

ONE

Section D Accident Details

Was anyone injured?	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
If, so in which vehicle and how?		
Date of accident *	29 / 11 / 17	Time 9.20 am
Location of accident *	SENATE ENTRANCE, PARLIAMENTARY DRIVE	
Was it reported to the Police?	<input checked="" type="checkbox"/> Yes if so give details below	<input type="checkbox"/> No
Police Station	ON SITE	
Officer's Name	Officer's Telephone	
Who do the Police consider responsible?		



Australian Government
COMCAR

COMCAR INFORMATION/LOST PROPERTY REPORT

This report is to be completed immediately upon identifying a situation that may require action by the Client Liaison Manager; on request from a COMCAR Manager or Supervisor; or following the discovery of lost property in a vehicle. The report must be lodged prior to the cessation of duty. You should note that this report can be released under the *Freedom of Information Act 1982* (FOI Act) and as such, must be an accurate and true account of the details. Please contact your COMCAR Manager or Supervisor if you have any questions or concerns regarding the completion of this document.

PART A – CLIENT DETAILS

Client Name:

s 22

Reservation Number:

Additional # of Pax:

PART B – CATEGORY

Type:
(Tick as appropriate)



ACCIDENT



BREAKDOWN



LATE VEHICLE



RESERVATIONS



NO CONTACT



COMPLAINT



FYI / OTHER



ALLOCATIONS

For FYI / Other, please
provide details:

PART C – LOST PROPERTY ONLY

Type:
(Tick as appropriate)



PHONE



BRIEFCASE



COMPUTER / TABLET



DOCUMENTS



GLASSES



WALLET / PURSE



CLOTHING



OTHER

For Other, please provide
details:

Do you know who left the
property in the vehicle?

☐ YES

☐ NO

State Allocator Advised?

☐ YES

☐ NO

Allocator's Name:

Date / Time Advised:

PART D – DETAILED DESCRIPTION

Date:

29.11.17

Time:

9.20am

Vehicle Rego:

s 22

Scheduled Pickup Time:

Actual Pickup Time:

Drop Time:

I APPROACHED THE BOLLARDS TO THE SENATE ENTRANCE OF PARLIAMENT HOUSE. I PUSHED THE INTERCOM BUTTON WAITED FOR A COUPLE OF SECONDS, THE BOLLARDS WENT DOWN, THE GREEN LIGHT CAME ON. I PROCEEDED THROUGH THE BOLLARDS WHILE THE SECOND SET OF BOLLARDS WERE GOING DOWN. I WAS ALMOST THROUGH THE FIRST SET OF BOLLARDS WHEN THEY CAME UP. THE SECOND SET OF BOLLARDS WERE DOWN. I STOPPED THE CAR BETWEEN THE TWO SETS OF BOLLARDS AND TURNED THE HAZARD LIGHTS ON.

I RANG THE TELEPHONE NUMBER ON THE

Continued overleaf...



Australian Government
Comcover

Comcover Member Services

Motor Vehicle Claim Report

Accident Description

Please provide a brief description of how the accident occurred

MALFUNCTION OF THE BOLLARDS WHILE DRIVING THROUGH THE SENATE ENTRANCE. PRESSED INTERCOM, THE LIGHT CAME ON. FIRST SET OF BOLLARDS WENT DOWN. THE GREEN CAR. WHILE DRIVING THROUGH THE SECOND SET OF BOLLARDS WERE GOING DOWN THE FIRST SET CAME UP + HIT THE CAR.

Please draw a diagram of accident at point of collision

Section F Witness

Witness to accident (attach list if necessary)

Name

s 22

Address

Telephone

Driver's Declaration

I declare that the use of the vehicle was authorised and the information provided in this claim form is correct in every respect

s 22

Driver's Name

Signature

Date

Please note

* Mandatory field

Once completed, please send this form to Comcover Member Services.



Attachments

One quote for repair to member vehicle
Police Report (if available)

s 22

Name of person reporting the claim

Signature of person reporting the claim

Date

Name of Agency Insurance Contact Officer

Signature of Agency Insurance Contact Officer

Date



LABOUR AS PER AUTHORITY 37570

1,355.39
323.50

Original

Parts

	<u>Qty</u>	<u>Part No.</u>	<u>Price</u>	<u>M/U</u>
1. FRONT SUSPENSION CROSSMEMB	s 22			
2. REAR SUSPENSION CROSS MEMBER				
3. REAR BUMPER COVER				
4. REAR BUMPER UNDERCOVER				
5. REAR BUMPER PARK DISTANCE SENSOR BEZEL				
6. REAR BUMPER MOULD - CHROME O/S				
7. REAR BUMPER MOULD - CHROME N/S				
8. FUEL TANK				
9. FUEL TANK MOUNTING BAND				
10. SPARE WHEEL WELL				
11. SPARE WHEEL WELL SEALANT (BETASEAL 300M				
12. N/S/R LOWER ARM				
13. EXHAUST SYSTEM ... REPORT				
14. REAR CROSSMEMBER MOUNTING BOLT				
15. EXHAUST HEAT SHIELD (CENTRE)				
16. TRANS TUNNEL TIE BRACKET REAR				
17. N/S/R SUSPENSION TRAILING LINK				
18. N/S/R SUSPENSION LOWER ARM				
19. N/S/R SUSPENSION UPPER ARM				
20. N/S/R SUSPENSION LINK				
21. N/S/R SUSPENSION JOINT LOWER ARM				
22. N/S/R SUSPENSION BUSH LOWER ARM				
23. N/S/R SUSPENSION JOINT UPPER ARM				
24. N/S/R SUSPENSION BUSH UPPER ARM				

s 22

s 22



s 22










































s 22























A close-up photograph of an aircraft's X member mount. The image shows a white, curved structural component with a yellow curved line and some brownish stains. A blue structural member is visible in the foreground, and a red component is visible in the background. The text "X MEMBER MOUNT" is overlaid in green.

X MEMBER MOUNT

