



# Geelong Consolidate Repairs T/A South City Panels Pty Ltd

112 Barwon Terrace  
South Geelong VIC 3220  
ABN: 29616462125  
B: 03 5223 2730  
Email: info@scpanels.com.au

## Request For Authority 89266

**Owner**  
**LIBBY COKER**

**Invoice to**  
**SG FLEET UNITY**  
PO Box 550  
Kotara NSW 2289  
ABN - 78 135 243 364

<b>Home Phone</b>	<b>Mobile Phone</b> s22	<b>Email</b>	<b>Start date</b> 1/09/2020	<b>End date</b>
<b>Estimate By</b> s22	<b>Estimate Date</b> 28/08/2020	<b>Claim Number</b> TBA	<b>Excess amount</b> 0.00	<b>Client contribution</b> 0.00

**VOLKSWAGEN TIGUAN 4 motion white**

s22

<b>Body style</b> station wagon	<b>Odometer</b> s22	<b>Paint Code</b>	<b>VIN</b> s22
<b>Cylinders</b>	<b>Manufactured</b> September 2018	<b>Trim Code</b>	<b>Engine Number</b>

**Remove + Refit @ s47G per Hour**

Front B/Bar Number Plate Frame  
Unitary Operation - Radiator Support

**Hours Amount**

s47G

**Repair @ s47G per Hour**

Front B/Bar Left End Lower

**Hours Amount**

s47G

**Paint @ s47G per Hour**

Front B/Bar  
Front B/Bar Small Individual Components  
Front B/Bar Pdc Sensor - Paint  
Front B/Bar Left End Lower  
Front B/Bar Right End Lower  
Front B/Bar Mould Left  
Front B/Bar Mould Right  
Grille  
Radiator Support Assembly  
Mix and Match  
Oven Allowance

**Hours Amount**

s47G

## Miscellaneous

Radiator Coolant - 6 & 8 Cyl (Green)  
Radiator Support Spray/Brush On Sealers  
Hose Clamps  
O-rings  
\*\*\*CODID-19 Sterilisation  
Nuts; Bolts & Clips  
Environment Levy  
Front Bar Driving Lights Wiring  
Front B/Bar Sensors & Wiring  
Radar Sensor / ADAS

s47G

Amount

s47G

## New Parts

Description	Supply	Part Number	Qty	Amount
Front B/Bar Cover	New	Genuine	1	s47G
Front B/Bar Reinforcement Lower	New	5NA807651D	1	
Front B/Bar Mould Centre - White	New	5NA853101FGRU	1	
Front B/Bar Lowe Air Deflector	New	5NA121341B	1	
Front B/Bar Lower Grille	New	5NA853677H041	1	
Front B/Bar Foglamp Bezel L/H (Upper)	New	5NA853665D041	1	
Front B/Bar Foglamp Bezel L/H (Lower)	New	5NA853211CGRU	1	
Front B/Bar Foglamp Bezel L/H (Chrome)	New	5NA853101C2ZZ	1	
Front B/Bar Mould Left (Goes under driving light)	New	5NA853101DGRU	1	
Radiator Support Assembly	New	Genuine	1	
LF Air Deflector	New	5NA121283P	1	
Total New Parts				

Amount

## Sublet

Air Conditioning Degas  
Air Conditioning Regas R34A  
Test & Report Radiators, Consensor, Pipes & Fans

s47G

Total Sublet

Total Labour

Total Parts / Other

Sub Total

Total Excluding GST

GST Amount

Total \$

4477.43

**From:** s22  
**Sent:** Wednesday, 2 September 2020 3:24 PM  
**To:** s22 (Geelong Consolidate Repairs T/A South City Panels Pty Ltd)  
**Cc:** 'libby.coker.mp@aph.gov.au'  
**Subject:** Comcover Claim: s22 - Vehicle No. s22 - Assessment Request

### Online Assessment Required

- Please arrange a motor vehicle assessment for our client's above vehicle as soon as possible - **AA with \$nil Excess**
- Repairs may be authorised up to the full amount of your assessment. If a supplementary quotation is submitted and this alters your assessment, please ensure a supplementary report is sent through to us.
- Details are as follows:

Department: Department of Finance

Contact/Phone: Libby Coker - s22

Date of Loss: 27/08/2020

Accident Description: Impact with Kangaroo

Repairer: South City Panels

Amount: \$4,477.43

- Please notify our client (see above contact details) once the assessment has been completed.
- Please note all assessments must be completed within 7 working days, unless unforeseen circumstances arise.

- If an assessment takes more than 7 working days, please provide a progress report via email as soon as possible to enable us to update the custodian of the vehicle.

Kind regards,

s22

[@comcover.com.au>](mailto:s22@comcover.com.au)

**From:** s22 (Geelong Consolidate Repairs T/A South City Panels Pty Ltd)  
[mailto:2003.au+y62vqsotrdkujcqbax7tbheom@mail.ibodyshop.com]  
**Sent:** Tuesday, 1 September 2020 3:40 PM  
**To:** Unity Fleet Admin  
**Subject:** Request For Authority - Claim TBA

Regards

South City Panels  
112 Barwon Tce, South Geelong  
Ph: 03 5223 2730 Fax: 03 5223 2947

**From:** s22  
**Sent:** Thursday, 17 September 2020 5:28 PM  
**To:** 'bookings@aamcommercial.com.au'  
**Subject:** Comcover Claim: s22 - Vehicle No. s22 - Assessment Request

### Online Assessment Required

- Please arrange a motor vehicle assessment for our client's above vehicle as soon as possible - **AA with \$nil Excess**
- Repairs may be authorised up to the full amount of your assessment. If a supplementary quotation is submitted and this alters your assessment, please ensure a supplementary report is sent through to us.
- Details are as follows:

Department: Department of Finance

Contact/Phone: Libby Coker - s22

Date of Loss: 27/08/2020

Accident Description: Impact with Kangaroo

Repairer: South City Panels

Amount: \$4,477.43

- Please notify our client (see above contact details) once the assessment has been completed.
- Please note all assessments must be completed within 7 working days, unless unforeseen circumstances arise.
- If an assessment takes more than 7 working days, please provide a progress report via email as

soon as possible to enable us to update the custodian of the vehicle.

Kind regards,

s22

[@comcover.com.au>](mailto:s22@comcover.com.au)

**From:** s22 (Geelong Consolidate Repairs T/A South City Panels Pty Ltd)  
[mailto:2003.au+y62vqsotrdkujcqbax7tbheaom@mail.ibodyshop.com]  
**Sent:** Tuesday, 1 September 2020 3:40 PM  
**To:** Unity Fleet Admin  
**Subject:** Request For Authority - Claim TBA

Regards

South City Panels  
112 Barwon Tce, South Geelong  
Ph: 03 5223 2730 Fax: 03 5223 2947

11/13/2020

iBodyshop Geelong Consolidate Repairs T/A South City Panels Pty Ltd



# Geelong Consolidate Repairs T/A South City Panels Pty Ltd

112 Barwon Terrace  
South Geelong VIC 3220

ABN: 29616462125

B: 03 5223 2730

Email info@cpanel.com.au

## Tax Invoice # s22

### Owner

**LIBBY COKER**

### Invoice to

**COMCOVER**

ABN 61 970 632 495

### Home Phone

### Mobile Phone

s22

### Email

### Start date

2/09/2020

### End date

30/09/2020

### Estimate Number

s22

### Invoice Date

30/09/2020

### Claim Number

s22

### Excess amount

0.00

### Client contribution

0.00

## VOLKSWAGEN TIGUAN 4 motion white

s22

### Body style

station wagon

### Odometer

s22

### Paint Code

### VIN

s22

### Cylinders

### Manufactured

September 2018

### Trim Code

### Engine Number

### Remove + Refit @ s47G per Hour

Front B/Bar Number Plate Frame

Unitary Operation - Radiator Support

### Hours

s47G

### Amount

### Repair @ s47G per Hour

Front B/Bar Left End Lower

### Hour

s47G

### Amount

### Paint @ s47G per Hour

Front B/Bar

Front B/Bar Small Individual Components

Front B/Bar Pdc Sensor - Paint

Front B/Bar Left End Lower

Front B/Bar Right End Lower

Front B/Bar Mould Left

Front B/Bar Mould Right

Grille

Radiator Support Assembly

### Hours

s47G

### Amount

Mix and Match  
Oven Allowance

s47G

Amount

**Miscellaneous**

Radiator Coolant - 6 & 8 Cyl (Green)  
Radiator Support Spray/Bru h On Sealer  
Hose Clamps  
O-rings  
\*\*\*CODID-19 Sterilisation  
Nut ; Bolt & Clip  
Environment Levy

s47G

**New Parts**

Description	Supply	Part Number	Qty	Amount
Front B/Bar Cover	New	Genuine	1	s47G
Front B/Bar Reinforcement Lower	New	5NA807651D	1	
Front B/Bar Mould Centre - White	New	5NA853101FGRU	1	
Front B/Bar Lowe Air Deflector	New	5NA121341B	1	
Front B/Bar Lower Grille	New	5NA853677H041	1	
Front B/Bar Foglamp Bezel L/H (Lower Outer)	New	5NA853665E041	1	
Front B/Bar Foglamp Bezel L/H (Lower)	New	5NA853211CGRU	1	
Front B/Bar Foglamp Bezel L/H (Chrome)	New	5NA853101C2ZZ	1	
Front B/Bar Mould Left (Goe under driving light)	New	5NA853101DGRU	1	
Radiator Support Assembly	New	Genuine	1	
LF Air Deflector	New	5NA121283P	1	
Front B/Bar Foglamp L/H	New	5NA941699B	1	
Front B/Bar Lower Spla h	New	5QF825235C	1	
Lower Grille Chrome Strip	New	5NA853101FGRU	1	
Front B/Bar Reinforcement	New	5NA807109J	1	
Air Cond. Condensor	New	geelong auto cooling	1	
Intercooler	New	geelong auto cooling	1	
Intercooler rubbers x2	New	geelong auto cooling	1	
<b>Total New Parts</b>				

**New Parts**

Description	Supply	Part Number	Qty	Amount
<u>Supplementary 1 Invoiced</u>				
Genuine coolant to fill Radiator	New	G12E050A2	2	s47G
<b>Total New Parts</b>				

Amount

**Sublet**

Air Conditioning Degas  
Air Conditioning Rega R34A  
Test & Report / Clean & Repair Radiators, Consensor, Pipes & Fans  
Supplementary 1 - Invoiced  
calibration

s47G

<b>Total Sublet</b>		s47G
<b>Total Excluding GST</b>		
<b>GST Amount</b>		
<b>Subtotal (including GST)</b>		
<b>Total Payable Including GST \$</b>		<b>6727.59</b>
Payment Terms - Due on Receipt: Due 30/09/2020		

BANK DETAILS

s22

**Comcover**

Locked Bag 4830 Melbourne VIC Australia 3001

Phone 1800 651 540

ABN 61970632495

**CLAIM DETAILS****\*\* Claim**s22  
Policy No.**Assessment Category****Division**

Light Motor

**Special Instructions for Repairer****\*\* Assessment party**

Insured

**Cover Type**

Market

**Assessment Type****Office**

Me bourne Team

**\* Excess**

NIL

**Policy Inception Date****INSPECTION DETAILS**

At the repairer

**Address**

112 Barwon Terrace

**Phone No.(W)**

03 5223 2730

**Suburb / Town**

South Geelong

**Fax****State/Territory**

VIC

**Mobile No.****Post Code**

3220

**VEHICLE DETAILS**

Authority Issued 01/10/2020

Make	Model	Series	Equip Level	Compliance Month/Year
VOLKSWAGEN	TIGUAN	162 TSI	HIGHLINE 5NA MY18	September 2018

Body Type	Engine Size	Colour	Paint Group	Paint Code
4D WAGON	T4	White	COB	

Rego Number	Expiry Date	Rego State	*Vehicle Condition
s22		VIC	Good

Odometer	Transmission
s22	7 SP AUTO DIRECT SHIFT

Engine Number	Tyre Serviceable	Brakes Serviceable

Depth Units	Axles Count
	2

Front	2(1L+1R)
Rear	2(1L+1R)

**Vehicle ID**

s22

**\*VIN/Chassis Number**

s22

DAMAGE LOCATION : Shade claim damage. circle and describe old damage. Also show direction of impact

**Type of Loss** : Collision**Non-Repairable Damage** :**Vehicle Moved** : No**\*Repair**

R &amp; R Labour s47G

Repair Labour

Paint Labour

Mech. Labour

Misc. Labour

**TOTAL LABOUR****Estimated Part**

(including Markup

Suble

Net Total

GS

Total

Less ITC

Less Exces

Less Contributio

**Estimated Total**

\$6,727.59

**Assessor Estimated**

s47G

**Total****\*Total Loss****Total Loss Date****Sum Insured /****Market Value****Cover Type****Market Value****\*Book Values****Trade Low****Trade****Retail****Avg.****\*Total Settlement****Settlement Amount****Salvage Value****TOTAL SETTLEMENT****Cash Settled****Certificate of****Compliance Required****\*Salvage Condition**

s22

s22

Assessor : AAMC  
 Assessor's Name : s22  
 PO Box 5752 Brendale QLD 4500  
 s22

Date Owner Advised  
 Inspection Date 18/09/2020

Type of Loss : Collision  
 Incident Type Code : Impact (I)

Butterfly & Impact Codes					
<p>O - Old Damage X - New Damage</p>	1 PASSENGER FRONT A - HEAVY PANEL	13 RIGHT REAR	25 B PILLAR DRIVER	37 SUSPENSION (DRIVER REAR)	
	2 DRIVER FRONT A - HEAVY PANEL	14 WHOLE VEHICLE	26 C PILLAR PASSENGER	38 AIRBAG FRONT	
	3 DRIVER SIDE	15 FLOOR PAN (PASSENGER FR...	27 C PILLAR DRIVER	39 AIRBAG SIDE	
	4 DRIVER REAR	16 FIRE WALL	28 D PILLAR PASSENGER	40 AIRBAG CURTAIN	
	5 PASSENGER REAR	17 CHASSIS/STRUCTURAL RAIL...	29 D PILLAR DRIVER	41 SEAT BELT PRE-TENSIONER	
	6 PASSENGER SIDE	18 FLOOR PAN (DRIVER REAR)	30 ENGINE BLOCK (CRACKED, ...	42 BATTERY PACK	
	7 ENGINE	19 FLOOR PAN (DRIVER FRONT)	31 TRANSMISSION CASE	43 TOW POINT	
	8 ROOF	20 FLOOR PAN (PASSENGER RE...	32 DIFFERENTIAL CASE	44 AUX EQUIPMENT	
	9 INTERIOR	21 CHASSIS/STRUCTURAL RAIL...	33 AXLE HOUSING	45 HYDRAULIC OR OTHER LIFT...	
	10 FRONT	22 A PILLAR PASSENGER	34 SUSPENSION (PASSENGER F...	46 ROLL-OVER PROTECTIVE ST...	
	11 REAR	23 A PILLAR DRIVER	35 SUSPENSION (DRIVER FRONT)		
	12 LEFT REAR	24 B PILLAR PASSENGER	36 SUSPENSION (PASSENGER R...		
<p>**15 FLOOR PAN (PASSENGER FRONT)    **20 FLOOR PAN (PASSENGER REAR)    **30 ENGINE BLOCK (CRACKED, FRACTURED)    **36 SUSPENSION (PASSENGER REAR)</p> <p>**17 CHASSIS/STRUCTURAL RAILS (PASSENGER)    **21 CHASSIS/STRUCTURAL RAILS (DRIVER)    **34 SUSPENSION (PASSENGER FRONT)</p>					

## ASSESSOR COMMENT (NOT VISIBLE TO THE REPAIRER)

We have completed an assessment of this vehicle.  
 The damage appears consistent with the claim description.  
 We have now authorised repairs.  
 The claimant has been updated accordingly.  
 \*\*\* The repairer has advised of a parts delay on front Bumper. Part is Ex Germany\*\*\*\*

\*\*\*\*\*Supplementary\*\*\*\*\*  
 We have now received a supplementary estimate from the repairer.  
 The supplementary appears in order, so we have issued the repairer with an authority to proceed. Invoices are attached in images.  
 The costs associated with this supplementary are detailed earlier in our report.  
 We do not recommend any increase to the repair reserve at this stage.

## REPAIRER DETAILS

South City Panels	ACN	License No.	
ABN			
29 616 462 125			
Address	Suburb / Town	State/Territory	Post Code
112 Barwon Terrace 112 Barwon Terrace	South Geelong	VIC	3220
Phone No.	Fax	Mobile No.	
03 5223 2730			
E-mail			
info@scpanels.com.au			

## ASSESSMENT DETAILS

Inspection Type Initial Inspection

Assessment Type  
 Inspection Date 18/09/2020

Assessor AAMC  
 ABN 51 101 934 801  
 Assessor Name s22

Address  
Suburb  
State/Territory  
Country AUSTRALIA  
Post Code  
Mobile No.  
Phone No.(H)  
Phone No.(W) s22  
Email @aamcommercial.com.au  
Fax

Estimate No. s22 Assessed Yes Assessed Date 01/10/2020 Amount \$6397.59  
Quote Date 27/08/2020 Authority Issued Yes Issued Date 01/10/2020

Invoice No. Invoice Status Date  
Approved by Approved Amount \$

Inspection Type Initial Inspection Assessment Type  
Inspection Date 18/09/2020

Assessor AAMC  
ABN 51 101 934 801  
Assessor Name s22  
Address  
Suburb  
State/Territory  
Country AUSTRALIA  
Post Code  
Mobile No.  
Phone No.(H)  
Phone No.(W) s22  
Email @aamcommercial.com.au  
Fax

Estimate No. s22 Assessed Yes Assessed Date 01/10/2020 Amount s47G  
Quote Date 27/08/2020 Authority Issued Yes Issued Date 01/10/2020

Invoice No. Invoice Status Date  
Approved by Approved Amount \$  
Authorised Labour Amount

Assessment Type Type of Loss Collision  
Inspection Date 18/09/2020 Salvage Value \$0.00  
Inspection Type Initial Inspection Out Date  
In Date Owner Contribution \$0.00  
Estimated days to repair 0 Owner Advised  
Non-Repairable Damage Assessor Reserve \$8,500.00  
Total Loss No Total Loss Date Manufactures Data Ref. CURRENT INDUSTRY REPAIR  
STANDARDS  
Salvage Reference Vehicle pick up Date/Time  
Type of Total Loss WOVN  
Authority Comment

### South City Panels

112 Barwon Terrace  
South Geelong VIC Australia 3220  
Phone No.(w) 03 5223 2730  
ABN 29 616 462 125

Contact s22  
Contact No.

Estimate No. s22

Remove & Replace RemoveAndRefit@ s47G

Description	Quoted Rate s47G	Assessed Rate s47G	OK	Assessor Note	Est. Hours	Ass. Hours	Est. \$	Ass. \$
Front B/Bar Number Plate Frame								
Unitary Operation - Radiator Suppor								
Total					s47G			

Repair Repair s47G

Description	Quoted Rate s47G	Assessed Rate s47G	OK	Assessor Note	Est. Hours	Ass. Hours	Est. \$	Ass. \$
Front B/Bar Left End Lower								
Total					s47G			

s22

s22

Paint Paint@s47G

Quoted Rate	Assessed Rate	OK	Est. Hours	Ass. Hours	Est. \$	Ass. \$
Description	Assessor Note					
Front B/Bar			s47G			
Front B/Bar Small Individual Compon						
Front B/Bar Pdc Sensor - Paint						
Front B/Bar Left End Lower						
Front B/Bar Right End Lower						
Front B/Bar Mould Left						
Front B/Bar Mould Right						
Grille						
Radiator Support Assembly						
Mix and Match						
Oven Allowance						
Total						

Miscellaneous

Quoted Rate	Assessed Rate	OK	Est. Hours	Ass. Hours	Est. \$	Ass. \$
Description	Assessor Note					
Radiator Coolant - 6 & 8 Cyl (Green			s47G			
Radiator Support Spray/Brush On Sea						
Hose Clamps						
O-rings						
***COD D-19 Sterilisation						
Nuts, Bolts & Clips						
Environment Levy						
Front Bar Driving Lights Wiring						
Front B/Bar Sensors & Wiring						
Radar Sensor / ADAS						
Total						
Total Labour						

Parts (Part Comparison Enabled)

Description	Assessor Note	Part No	Part Description	Src	Qty	Est. \$	MUE	Ass. \$	Part \$	MUA	Ass.
Front B/Bar Cover	✓	Genuine	Genuine	OEM	1	s47G					
Front B/Bar Reinforcement Lower	✓	5NA807651D	F BAR STIFFENER	OEM	1						
Front B/Bar Mould Centre - White	✓	5NA853101FGf5NA853101FGRU		OEM	1						
Front B/Bar Lowe Air Deflector	✓	5NA121341B	AIR DEFLECTOR	OEM	1						
		LWR-110TDI, 132TSI									
Front B/Bar Lower Grille	✓	5NA853677H045NA853677H041		OEM	1						
Front B/Bar Foglamp Bezel L/H (Uppe	✓	5NA853665D045NA853665D041		OEM	1						
Front B/Bar Foglamp Bezel L/H (Lowe	✓	5NA853211CGi5NA853211CGRU		OEM	1						
Front B/Bar Foglamp Bezel L/H (Chro	✓	5NA853101C2Z5NA853101C2ZZ		OEM	1						
Front B/Bar Mould Left (Goes under	✓	5NA853101DGi5NA853101DGRU		OEM	1						
Radiator Support Assembly	✓	Genuine	Genuine	OEM	1						
LF Air Deflector	✓	5NA121283P	5NA121283P	OEM	1						
Front B/Bar Foglamp L/H	✓	5NA941699B	F BAR FOGLAMP N/S 5/17-	OEM	1						
Front B/Bar Lower Splash	✓	5QF825235C	ENGINE SPLASH TRAY -6/17	OEM	1						
Lower Grille Chrome Strip	✓	5NA853101FGf5NA853101FGRU		OEM	1						
Front B/Bar Reinforcement	✓	5NA807109J	F BAR RE NF -5/17	OEM	1						
Air Cond. Condensor	✓	geelong auto	geelong auto cooling	OEM	1						
		cooling									
Intercooler	✓	geelong auto	geelong auto cooling	OEM	1						
		cooling									
Intercooler rubbers x2	✓	geelong auto	geelong auto cooling	OEM	1						
		cooling									
Total						s47G					
Total (with Markup)											

Sublet

Description	Assessor Note	Est. \$	Ass. \$
Air Conditioning Degas		s47G	
Air Conditioning Regas R34A			
Test & Report / Clean & Repair Radi			
Total			
Net Total			

Original

	Quoted	Ass.	Adj.
R & R	s47G		
Repair			
Paint			
Mech.			
Mis.			
Total Labour			
Parts			
M/U			
Sublet			
Net Total			
GST 10.00 %			
Total	\$6397.59	\$6397.59	\$0.00

Supplement No. 1

Total Labour s47G

Parts (Part Comparison Enabled)

Description	Assessor Note	Part No	Part Description	Src	Qty	Est. \$	MUE	Ass. \$	Part \$	MUA Ass.
Genuine coolant to fill Radiator		✓ G12E050A2	G12E050A2	OEM		s47G				
Total										
Total (with Markup)										

Sublet

Description	Assessor Note	
calibration		
		Total
		Net Total

Supplement No. 1

	Quoted	Ass.	Adj.
R & R	s47G		
Repair			
Paint			
Mech.			
Mis.			
Total Labour			
Parts			
M/U			
Sublet			
Net Total			
GST 10.00 %			
Total			

Quote Total

	Quoted	Ass.	Adj.
Total Labour	\$0.00	\$0.00	\$0.00
Net Total	\$0.00	\$0.00	\$0.00
GST	\$0.00	\$0.00	\$0.00
Total	\$0.00	\$0.00	\$0.00